



Carlos Rosario PCS (Sonia Gutierrez) - Lead in Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation											
Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Filter Test ID	FT Final Results - Draw A (ppb)	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right					
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-001	Cooler	Ground	In hallway adjacent to room SG012	High	Left	WF-112017-043001-01	5/2/18	FT-FY18-112017-043001	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-002	Bottle Filler	Ground	In hallway adjacent to room SG012	High	Left	WF-112017-043002-01	5/2/18	FT-FY18-112017-043002	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-003	Cooler	Ground	In hallway adjacent to room SG012	Low	Right	WF-112017-043003-01	5/2/18	FT-FY18-112017-043003	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-004	Cooler	1	In hallway adjacent to room SG107	High	Left	WF-112017-043004-01	5/2/18	FT-FY18-112017-043004	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-005	Bottle Filler	1	In hallway adjacent to room SG107	High	Left	WF-112017-043005-01	5/2/18	FT-FY18-112017-043005	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-006	Cooler	1	In hallway adjacent to room SG107	Low	Right	WF-112017-043006-01	5/2/18	FT-FY18-112017-043006	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-007	Cooler	2	In hallway adjacent to room 209	High	Left	WF-112017-043007-01	5/2/18	FT-FY18-112017-043007	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-008	Bottle Filler	2	In hallway adjacent to room 209	High	Left	WF-112017-043008-01	5/2/18	FT-FY18-112017-043008	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-009	Cooler	2	In hallway adjacent to room 209	Low	Right	WF-112017-043009-01	5/2/18	FT-FY18-112017-043009	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-012	Break Room	2	In staff lounge 217	-	-	WF-112017-043012-01	5/2/18	FT-FY18-112017-043012	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-013	Cooler	3	In hallway adjacent to room 319	High	Left	WF-112017-043013-01	5/2/18	FT-FY18-112017-043013	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-014	Bottle Filler	3	In hallway adjacent to room 319	High	Left	WF-112017-043014-01	5/2/18	FT-FY18-112017-043014	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-015	Cooler	3	In hallway adjacent to room 319	Low	Right	WF-112017-043015-01	5/2/18	FT-FY18-112017-043015	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-016	Health Suite	3	In nurse suite 311A	-	-	WF-112017-043016-01	5/2/18	FT-FY18-112017-043016	1.4	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-017	Cooler	3	In main hall 325	High	Left	WF-112017-043017-01	5/2/18	FT-FY18-112017-043017	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-018	Bottle Filler	3	In main hall 325	High	Left	WF-112017-043018-01	5/2/18	FT-FY18-112017-043018	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-019	Cooler	3	In main hall 325	Low	Right	WF-112017-043019-01	5/2/18	FT-FY18-112017-043019	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-020	Food Prep Sink	3	In SG 306 by window	-	-	WF-112017-043020-01	5/2/18	FT-FY18-112017-043020	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-021	Bottle Filler	2	In room SG 220	-	-	WF-112017-043021-01	5/2/18	FT-FY18-112017-043021	<1	<1
Carlos Rosario PCS [Sonia Gutierrez]	WS-043-022	Bottle Filler	2	In break room SG 217	-	-	WF-112017-043022-01	5/2/18	FT-FY18-112017-043022	<1	<1